



## RETAIL FIRST

### WHAT VALUE WAS ADDED FOR THE CUSTOMER

- Height Dynamics was able to access and clean the upper roof structural steel work utilising approved Industrial Rope Access techniques.
- Cleaning was conducted during centre night closure periods with no interruption to tenant trading and no costly installation of scaffold access systems.
- Due to the minimal infrastructure required by this method, there was no costly downtime setting up access systems or unsightly structures installed which enabled the work to be done discreetly.

## CASE STUDY

### CUSTOMER NAME

Retail First

### LOCATION

Main Atrium of Toowong Shopping Centre

### SCOPE OF WORKS

Conduct high steel cleaning above atrium void.

### OUTCOMES

The use of Industrial Rope Access techniques to hand clean the area of the atrium void with no costly downtime to the centre or unsightly scaffolding or safety structures.

